

ECO INSPECTION CERTIFICATE

Premium

Order ID : 51188

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Jatin	Inspection Date : 2019-03-22	Valid Till : 2019-06-22	Inspected By  Gagan Gurawaliya
-----------------------	---------------------------------	----------------------------	---

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
550+ vehicle inspected
1+ years experience

Mitsubishi Pajero Sport 4X4 MT, 2013



VEHICLE INFORMATION			
MAKE	MITSUBISHI	TRANSMISSION TYPE	MANUAL
MODEL	PAJERO SPORT	REGISTRATION NO.	HR26BY0906
YEAR	2013	VIN/CHASIS NUMBER	000541
TRIM	4X4 MT	KMS RUN	131262
COLOR	WHITE	INSURANCE EXPIRY	2020-1-11
BODY TYPE	SUV	LOCATION	SEC21 GGN
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	YES
		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

9,30,224




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 16,300



Category	Estimated Spend
Interior	0
Wheel	0
Test Drive	0
Exterior	16,300
Hood	0

Ordered by: Jatin | Inspected date: 2019-03-22

Order Id: 51188

Overall Score



7/10



9,30,224



INTERIOR






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD CONDITION	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION	0
HANDBRAKE	7	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	7	GOOD CONDITION	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	GOOD CONDITION	0
A/C VENTS & HEATER	7	GOOD CONDITION	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES)	7	GOOD CONDITION	0
HAZARD LIGHT	7	GOOD CONDITION	0



IMAGES






TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION	0
BRAKE PERFORMANCE	7	GOOD CONDITION	0
CLUTCH PERFORMANCE	7	GOOD CONDITION	0
ENGINE NOISE	7	GOOD CONDITION	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	7	GOOD CONDITION	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD CONDITION	0
REAR VIEW CAMERA (YES)	7	GOOD CONDITION	0



IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	MAX	0
ENGINE OIL	7	MAX	0
COOLANT LEVEL	7	MAX	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

 IMAGES



Ordered by: Jatin | Inspected date: 2019-03-22

Order Id: 51188

Overall Score  **7/10**



9,30,224

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	6	MINOR SCRATCHES	1000
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD CONDITION	0
FOG LAMPS	7	GOOD CONDITION	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	6	MINOR SCRATCHES	800
LH FRONT DOOR	6	MINOR SCRATCHES AND DENT	1500
LH REAR DOOR	6	MINOR SCRATCHES AND DENT	1500
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	6	MINOR DENT AND SCRATCHES	1500
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	6	MINOR SCRATCHES	1000
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH QUARTER PANEL	6	MINOR SCRATCHES	1000
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	6	MINOR SCRATCHES AND DENT	1500

RH FRONT DOOR

6

MINOR SCRATCHES AND
DENT

1500

Ordered by: Jatin | Inspected date: 2019-03-22

Order Id: 51188

Overall Score



7/10



9,30,224



EXTERIOR (CONTINUED)





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	MINOR DENT AND SCRATCHES	1000
BODY RUST	7	GOOD CONDITION	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0
TAIL LIGHT	5	RHS TAIL LAMP NEED TO REPLACE	4000



IMAGES








NEED ATTENTION



DOCUMENTS



DESCRIPTION

minor scratches and dent both bumpers already painted rhs quarterpanel already painted

Ordered by: Jatin | Inspected date: 2019-03-22

Order Id: 51188

Overall Score















7/10



9,30,224

IMAGES





Ordered by: Jatin | Inspected date: 2019-03-22

Order Id: 51188

Overall Score



7/10



9,30,224

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.