

ECO INSPECTION CERTIFICATE

Premium

Order ID : 53864

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : MOHAMMED ABDUL	Inspection Date : 2019-03-28	Location : HYDERABAD	Inspected By Sharan Kumar Bandi
---------------------------------------	--	--------------------------------	--

7/10 Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 113 does not need attention
- 1 Owner , 9 Years Vehicle Age
- No Accidental History

Verified Technician
72+ vehicle inspected
1+ years experience

Tata Nano STD, 2010



VEHICLE INFORMATION

MAKE	TATA	ENGINE NUMBER	273MPFL01E
MODEL	NANO	REGISTRATION NO.	AP09BZ0184
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	MAT612203AKE04501
TRIM	STD	ODOMETER READING	26115
COLOR	BLUE	INSURANCE EXPIRY	2018-6-14
BODY TYPE	SEDAN	VEHICLE PASSING	
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

43,928




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 21,702



Ordered by: MOHAMMED ABDUL | Inspected date: 2019-03-28

Order Id: 53864

Overall Score **7/10**




43,928

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	9		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	9		0
HORN	10		0
HANDBRAKE	9		0
STEERING-MOUNTED CONTROLS	9		0
PEDALS	9		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	8		0
SPEAKERS & MUSIC SYSTEM	0	NO SOUND SYSTEM	1900
CENTRAL LOCK	0	NO CENTRAL LOCK	2500
A/C VENTS & HEATER	0	NO AC	5000
CUP HOLDERS	0	NO HOLDERS	1

IMAGES



Ordered by: MOHAMMED ABDUL | Inspected date: 2019-03-28

Order Id: 53864

Overall Score **7/10**




43,928

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES







WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0
TYRES	3	BAD	7000

 IMAGES



 NEED ATTENTION 



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	9		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: MOHAMMED ABDUL | Inspected date: 2019-03-28

Order Id: 53864

Overall Score  **7/10**



43,928

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
HEAD LIGHTS	9		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	9		0
LH FRONT DOOR	9		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	9		0
TRUNK LID/TAIL GATE	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	7		0
RH REAR DOOR	8		0
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0

Ordered by: MOHAMMED ABDUL | Inspected date: 2019-03-28

Order Id: 53864

Overall Score **7/10**



43,928

EXTERIOR (CONTINUED)



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	8		0
PAINT CONDITION	9		0
FRONT BUMPER	3	DAMAGED NEED TO BE CHANGED	2500
TAIL LIGHT	5	NEED TO BE CHANGED	2800
LUGGAGE COMPARTMENT LIGHT	0	NO LUGGAGE COMPARTMENT	1



IMAGES



NEED ATTENTION ⚠️



DOCUMENTS



DESCRIPTION

normal

Ordered by: MOHAMMED ABDUL | Inspected date: 2019-03-28

Order Id: 53864

Overall Score



7/10



43,928

IMAGES





Ordered by: MOHAMMED ABDUL | Inspected date: 2019-03-28

Order Id: 53864

Overall Score



7/10



43,928

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.