

ECO INSPECTION CERTIFICATE

Premium

Order ID : 56274

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Akash	Inspection Date : 2019-04-16	Location : GHAZIABAD
-----------------------	---------------------------------	-------------------------

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 114 does not need attention
- ✓ 2 Owners , 10 Years Vehicle Age
- ✓ No Accidental History

Inspected By

Verified Technician
212+ vehicle inspected
1+ years experience

Kishan Kumar

Ford Endeavour 3.0l 4x4 At, 2009



VEHICLE INFORMATION

MAKE	FORD	ENGINE NUMBER	20798
MODEL	ENDEAVOUR	REGISTRATION NO.	DL3CAN2726
MFG. DATE	2008-11-11	VIN/CHASSIS NUMBER	20798
TRIM	3.0L 4X4 AT	ODOMETER READING	95326
COLOR	WHITE	INSURANCE EXPIRY	2019-4-16
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,87,428




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 2,850



Ordered by: Akash | Inspected date: 2019-04-16

Order Id: 56274

Overall Score



6/10



4,87,428



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	AVERAGE CONDITION	0
DOOR HINGES	6	AVERAGE CONDITION	0
CARPET & FLOOR MAT	6	AVERAGE CONDITION	0
SEAT & SEAT BELT	6	AVERAGE CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	AVERAGE CONDITION	0
HORN	7	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	7	GOOD MUSIC	0
HANDBRAKE	7	GOOD CONDITION	0
PEDALS	6	AVERAGE CONDITION	0
A/C VENTS & HEATER	6	AVERAGE COOLING	0
CUP HOLDERS	7	GOOD CONDITION	0
ODOMETER	6	AVERAGE CONDITION	0
POWER WINDOWS (YES)	6	AVERAGE CONDITION	0
HAZARD LIGHT	6	AVERAGE CONDITION	0
STEERING-MOUNTED CONTROLS	0	NA	0
CENTRAL LOCK	0	NA	0
NAVIGATION (YES)	0	NA	0



IMAGES



Ordered by: Akash | Inspected date: 2019-04-16

Order Id: 56274

Overall Score **6/10**



4,87,428

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	AVERAGE CONDITION	0
BRAKE PERFORMANCE	6	AVERAGE CONDITION	0
CLUTCH PERFORMANCE	6	AVERAGE CONDITION	0
ENGINE NOISE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	6	AVERAGE CONDITION	0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	6	AVERAGE CONDITION	0
REAR VIEW CAMERA (YES)	6	AVERAGE CONDITION	0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD CONDITION	0
SPARE TYRE (YES)	6	AVERAGE CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE CONDITION	0
RH APRON	6	AVERAGE CONDITION	0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	GOOD CONDITION	0
ENGINE OIL	7	GOOD VISCOSITY	0
COOLANT LEVEL	7	MAXIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	6	AVERAGE CONDITION	0

 IMAGES



Ordered by: Akash | Inspected date: 2019-04-16

Order Id: 56274

Overall Score  **6/10**



4,87,428

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	6	SCRATCHES	450
GRILLE	6	AVERAGE CONDITION	0
TURN SIGNAL	6	AVERAGE CONDITION	0
FOG LAMPS	6	AVERAGE CONDITION	0
HOOD	6	AVERAGE CONDITION	0
PILLAR	6	AVERAGE CONDITION	0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	AVERAGE CONDITION	0
LH FENDER	6	SCRATCHES	300
LH FRONT DOOR	6	AVERAGE CONDITION	0
LH REAR DOOR	6	AVERAGE CONDITION	0
LH RUNNING BOARD	6	AVERAGE CONDITION	0
FUEL LID	6	AVERAGE CONDITION	0
REAR WINDSHIELD	6	AVERAGE CONDITION	0
REAR BUMPER	6	AVERAGE CONDITION	0
TAIL LIGHT	6	AVERAGE CONDITION	0
TRUNK LID/TAIL GATE	6	AVERAGE CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	AVERAGE CONDITION	0
RH QUARTER PANEL	6	SCRATCHES	300
RH RUNNING BOARD	6	AVERAGE CONDITION	0
RH REAR DOOR	6	AVERAGE CONDITION	0
RH FRONT DOOR	6	AVERAGE CONDITION	0
RH FENDER	6	AVERAGE CONDITION	0

Ordered by: Akash | Inspected date: 2019-04-16

Order Id: 56274

Overall Score



6/10



4,87,428



EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6	AVERAGE CONDITION	0
ROOF (REGULAR)	6	AVERAGE CONDITION	0
PAINT CONDITION	6	AVERAGE CONDITION	0
HEAD LIGHTS	5	LEFT HEAD LIGHT NOT WORKING NEED TO CHECK AND REPAIR	300
LH QUARTER PANEL	5	DENT NEED TO BE REPAIR	1500



IMAGES





NEED ATTENTION ⚠️



DOCUMENTS



DESCRIPTION

all scratches and dent need to be repair

Ordered by: Akash | Inspected date: 2019-04-16

Order Id: 56274

Overall Score





6/10



4,87,428

 IMAGES





www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by **droom**.in

Ordered by: Akash | Inspected date: 2019-04-16

Order Id: 56274

Overall Score



6/10



4,87,428

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.