

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 60029

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Radhey	Inspection Date : 2019-04-10	Valid Till : 2019-07-11	Inspected By  <b>Gagan Gurawaliya</b> Verified Technician 612+ vehicle inspected 1+ years experience
------------------------	---------------------------------	----------------------------	---

## 7/10

Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 121 does not need attention
- 2 Owners , 14 Years Vehicle Age
- No Accidental History

## Mercedes-Benz E-Class 200K CLASSIC, 2005



VEHICLE INFORMATION			
MAKE	MERCEDES-BENZ	TRANSMISSION TYPE	AUTOMATIC
MODEL	E-CLASS	REGISTRATION NO.	HR26CQ5408
YEAR	2005	VIN/CHASIS NUMBER	797733
TRIM	200K CLASSIC	KMS RUN	95327
COLOR	SILVER	INSURANCE EXPIRY	2020-3-23
BODY TYPE	SEDAN	LOCATION	DLFPHASE2 GGN
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

# 3,81,773

Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
Interior	<div style="width: 70%;"></div> 7 / 10	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> </div> <div style="display: flex; justify-content: space-around; margin-top: 10px;"> <div style="text-align: center;"> Interior</div> <div style="text-align: center;"> Wheel</div> <div style="text-align: center;"> Test Drive</div> <div style="text-align: center;"> Exterior</div> <div style="text-align: center;"> Hood</div> </div>
Wheel	<div style="width: 70%;"></div> 7 / 10	
Test Drive	<div style="width: 80%;"></div> 8 / 10	
Exterior	<div style="width: 70%;"></div> 7 / 10	
Hood	<div style="width: 70%;"></div> 7 / 10	

Ordered by: Radhey | Inspected date: 2019-04-10

Order Id: 60029

Overall Score  **7/10**



**3,81,773**

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD CONDITION	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION	0
HANDBRAKE	7	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	7	GOOD CONDITION	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	GOOD CONDITION	0
A/C VENTS & HEATER	7	GOOD CONDITION	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES)	7	GOOD CONDITION	0
HAZARD LIGHT	7	GOOD CONDITION	0

## IMAGES



Ordered by: Radhey | Inspected date: 2019-04-10

Order Id: 60029

Overall Score  **7/10**




**3,81,773**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION	0
BRAKE PERFORMANCE	7	GOOD CONDITION	0
CLUTCH PERFORMANCE	7	GOOD CONDITION	0
ENGINE NOISE	7	GOOD CONDITION	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	7	GOOD CONDITION	0
CRUISE CONTROL (YES)	7	GOOD CONDITION	0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES



## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	MAX	0
ENGINE OIL	7	MAX	0
COOLANT LEVEL	7	MAX	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

 IMAGES



Ordered by: Radhey | Inspected date: 2019-04-10

Order Id: 60029

Overall Score  **7/10**



**3,81,773**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	6	MINOR SCRATCHES AND CRACK	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD CONDITION	0
FOG LAMPS	7	GOOD CONDITION	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	6	MINOR CRACK	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	6	MINOR SCRATCHES	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	6	MINOR SCRATCHES	0
TAIL LIGHT	6	RHS NEED TO REPLACE	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	6	MINOR SCRATCHES	0

Ordered by: Radhey | Inspected date: 2019-04-10

Order Id: 60029

Overall Score  **7/10**



**3,81,773**

**EXTERIOR (CONTINUED)**

**7/10**






INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0
BODY RUST	7	GOOD CONDITION	0
ROOF (SUN ROOF)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0

**IMAGES**





## DOCUMENTS



## DESCRIPTION

minor scratches car already painted

Ordered by: Radhey | Inspected date: 2019-04-10

Order Id: 60029

Overall Score




7/10













3,81,773

IMAGES







Ordered by: Radhey | Inspected date: 2019-04-10

Order Id: 60029

Overall Score



7/10



3,81,773

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.