

ECO INSPECTION CERTIFICATE

Premium

Order ID : 61301

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sushil	Inspection Date : 2019-05-11	Location : HISAR
------------------------	---------------------------------	---------------------

7/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **119** does not need attention
- ✔ **1** Owner , **12** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

75+ vehicle inspected
1+ years experience

ARVIND KUMAR

Tvs Apache 150CC, 2007



VEHICLE INFORMATION			
MAKE	TVS	ENGINE NUMBER	29920
MODEL	APACHE	REGISTRATION NO.	HR20N6527
YEAR	2007	VIN/CHASSIS NUMBER	20342
TRIM	150CC	ODOMETER READING	84916
COLOR	RED	INSURANCE EXPIRY	2019-5-2
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	ORIGINAL
DENT	NO	INSURANCE COPY AVAILABLE	NO
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

11,672

orangebookvalue.com

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

	Tyre	<div style="width: 70%; background-color: green;"></div>	7 / 10
	Control	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
	Light	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
	Oil	<div style="width: 70%; background-color: green;"></div>	7 / 10
	Chassis	<div style="width: 70%; background-color: green;"></div>	7 / 10
	Stand	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0

0

Tyre

0

Control

0

Light

0

Oil

0

Chassis

0

Stand

www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score



7/10



11,672



TYRE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	GOOD	0
REAR TYRE CONDITION & AIR PRESSURE	7	GOOD	0
WHEEL SPOKES FRONT	6	NEUTRAL	0
WHEEL SPOKES REAR	7	GOOD	0
WHEEL RIM FRONT	6	NEUTRAL	0
WHEEL RIM REAR	7	GOOD	0
WHEEL BEARINGS FRONT	7	GOOD	0
WHEEL BEARINGS REAR	6	NEUTRAL	0
WHEEL SEALS FRONT	7	GOOD	0
WHEEL SEALS REAR	7	GOOD	0
BRAKE FUNCTION FRONT	6	NEUTRAL	0
BRAKE FUNCTION REAR	7	GOOD	0
BRAKES CONDITION FRONT	6	NEUTRAL	0
BRAKES CONDITION REAR	7	GOOD	0

IMAGES





Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score **7/10**




11,672

STAND

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	NEUTRAL	0
CENTRE STAND RETENTION	7	GOOD	0
SIDE STAND CONDITION	6	NEUTRAL	0
SIDE STAND RETENTION	7	GOOD	0

IMAGES




CONTROL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	GOOD	0
LEVERS & PEDAL CONDITION	6	NEUTRAL	0
PIVOTS	7	GOOD	0
CABLES CONDITION	6	NEUTRAL	0
CABLES ROUTING	6	NEUTRAL	0
HOSES CONDITION	7	GOOD	0
HOSES ROUTING	6	GOOD	0
THROTTLE OPERATION	7	GOOD	0

IMAGES




OIL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7	GOOD	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7	GOOD	0
LEVELS - HYDRAULIC FLUID (YES)	6	NEUTRAL	0
LEVELS - COOLANT (YES)	7	GOOD	0
LEVELS - FUEL	6	NEUTRAL	0
LEAKS - ENGINE OIL	7	GOOD	0
LEAKS - GEAR OIL	6	NEUTRAL	0
LEAKS - HYDRAULIC FLUID	7	GOOD	0
LEAKS - COOLANT	6	NEUTRAL	0
LEAKS - FUEL	7	GOOD	0

IMAGES



Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score



7/10



11,672




 LIGHT



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	NEUTRAL	0
BATTERY VENT TUBE	7	GOOD	0
HEADLAMP CONDITION	6	NEUTRAL	0
TAILLAMP/BRAKELAMP CONDITION	6	NEUTRAL	0
TAILLAMP/BRAKELAMP OPERATION	7	GOOD	0
TURN SIGNALS OPERATION FRONT LEFT	6	NEUTRAL	0
TURN SIGNALS OPERATION REAR LEFT	7	GOOD	0
TURN SIGNALS OPERATION REAR RIGHT	7	GOOD	0
SWITCHES OPERATION	7	GOOD	0
MIRRORS AIM	6	MISSING	0
LENSES & REFLECTORS CONDITION	7	GOOD	0
WIRING CONDITION	7	GOOD	0
WIRING ROUTING	7	GOOD	0
TURN SIGNALS OPERATION FRONT RIGHT	3	700	0
MIRRORS CONDITION	0	MISSING	0

 IMAGES



Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score **7/10**



11,672

NEED ATTENTION



CHASSIS

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7	GOOD	0
FRAME STEERING-HEAD BEARINGS	6	NEUTRAL	0
FRAME SWINGARM BUSHINGS	7	GOOD	0
SUSPENSION FRONT FORKS LEFT	6	NEUTRAL	0
SUSPENSION FRONT FORKS RIGHT	7	GOOD	0
SUSPENSION REAR SHOCKS LEFT	6	NEUTRAL	0
SUSPENSION REAR SHOCKS RIGHT	7	GOOD	0
CHAIN/BELT TENSION	7	GOOD	0
CHAIN/BELT LUBRICATION	6	NEUTRAL	0
CHAIN/BELT SPROCKETS	7	GOOD	0
FASTENERS THREADED	7	GOOD	0
FASTENERS CLIPS & COTTER PINS	7	GOOD	0
ENGINE	6	NEUTRAL	0
TRANSMISSION	7	GOOD	0

Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score



7/10



11,672

IMAGES



DOCUMENTS



DESCRIPTION

good

Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score




7/10



11,672

IMAGES



Ordered by: sushil | Inspected date: 2019-05-11

Order Id: 61301

Overall Score



7/10



11,672

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.