

ECO INSPECTION CERTIFICATE

Premium

Order ID : 63672

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Kalyan	Inspection Date : 2019-04-19	Location : SALT LAKE, SEC 2	Inspected By Labani Ray Naskar
-------------------------------	--	---------------------------------------	---

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **3** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

66+ vehicle inspected
1+ years experience

Mercedes-Benz Gla 200 CDI STYLE, 2016



VEHICLE INFORMATION			
MAKE	MERCEDES-BENZ	ENGINE NUMBER	3032465171
MODEL	GLA	REGISTRATION NO.	WB06L8008
MFG. DATE	2014-09-18	VIN/CHASSIS NUMBER	WDC1569082J062472
TRIM	200 CDI STYLE	ODOMETER READING	28315
COLOR	WHITE	INSURANCE EXPIRY	2019-5-15
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	70,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE (BUMPER TO BUMPER)	YES	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

Orange Book Value Not Available

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE			TOTAL ESTIMATE SPEND 0				
Interior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10	0	0	0	0	0
Wheel	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					
Test Drive	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					
Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					
Hood	<div style="width: 60%; background-color: yellow;"></div>	6 / 10					

Ordered by: Kalyan | Inspected date: 2019-04-19

Order Id: 63672

Overall Score



6/10



Orange Book Value Not Available



INTERIOR








6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION	0
DOOR HINGES	6	GOOD CONDITION	0
CARPET & FLOOR MAT	6	GOOD CONDITION	0
SEAT & SEAT BELT	6	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD CONDITION	0
HORN	6	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	6	GOOD CONDITION	0
HANDBRAKE	6	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	6	GOOD CONDITION	0
PEDALS	6	GOOD CONDITION	0
CENTRAL LOCK	6	GOOD CONDITION	0
A/C VENTS & HEATER	6	GOOD CONDITION	0
CUP HOLDERS	6	GOOD CONDITION	0
NAVIGATION (YES)	6	GOOD CONDITION	0
ODOMETER	6	GOOD CONDITION	0
POWER WINDOWS (YES)	6	GOOD CONDITION	0
HAZARD LIGHT	6	GOOD CONDITION	0



IMAGES





TEST DRIVE





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD CONDITION	0
BRAKE PERFORMANCE	6	GOOD CONDITION	0
CLUTCH PERFORMANCE	6	GOOD CONDITION	0
ENGINE NOISE	6	GOOD CONDITION	0
IGNITION SYSTEM	6	GOOD CONDITION	0
SUSPENSION PERFORMANCE	6	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	6	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	6	GOOD CONDITION	0
TRANSMISSION ENGAGE	6	GOOD CONDITION	0
CRUISE CONTROL (YES)	6	GOOD CONDITION	0
REAR PARKING SENSORS (YES)	6	GOOD CONDITION	0
REAR VIEW CAMERA (YES)	6	GOOD CONDITION	0



IMAGES





WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD CONDITION	0
SPARE TYRE (YES)	6	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD CONDITION	0

IMAGES



HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD CONDITION	0
RH APRON	6	GOOD CONDITION	0
RADIATOR	6	GOOD CONDITION	0
WIRING	6	GOOD CONDITION	0
BATTERY	6	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	GOOD CONDITION	0
ENGINE OIL	6	GOOD CONDITION	0
COOLANT LEVEL	6	GOOD CONDITION	0

BRAKE & COOLANT HOSE PIPES	6	GOOD CONDITION	0
UNDERCARRIAGE	6	GOOD CONDITION	0
EXHAUST SYSTEM	6	GOOD CONDITION	0

 IMAGES



Ordered by: Kalyan | Inspected date: 2019-04-19

Order Id: 63672

Overall Score



6/10



Orange Book Value Not Available



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD CONDITION	0
FRONT BUMPER	6	GOOD CONDITION	0
HEAD LIGHTS	6	GOOD CONDITION	0
GRILLE	6	GOOD CONDITION	0
TURN SIGNAL	6	GOOD CONDITION	0
FOG LAMPS	6	FOG LIGHT NOT AVAILABLE..	0
HOOD	6	GOOD CONDITION	0
PILLAR	6	GOOD CONDITION	0
FRONT WINDSHIELD	6	GOOD CONDITION	0
SIDE VIEW MIRRORS	6	GOOD CONDITION	0
LH FENDER	6	GOOD CONDITION	0
LH FRONT DOOR	6	GOOD CONDITION	0
LH REAR DOOR	6	GOOD CONDITION	0
LH RUNNING BOARD	6	GOOD CONDITION	0
LH QUARTER PANEL	6	GOOD CONDITION	0
FUEL LID	6	GOOD CONDITION	0
REAR WINDSHIELD	6	GOOD CONDITION	0
REAR BUMPER	6	GOOD CONDITION	0
TAIL LIGHT	6	GOOD CONDITION	0
TRUNK LID/TAIL GATE	6	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD CONDITION	0
RH QUARTER PANEL	6	GOOD CONDITION	0
RH RUNNING BOARD	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION	0

Ordered by: Kalyan | Inspected date: 2019-04-19

Order Id: 63672

Overall Score



6/10



Orange Book Value Not Available



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD CONDITION	0
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	GOOD CONDITION	0
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD CONDITION	0





IMAGES





 DOCUMENTS



 DESCRIPTION

All over condition is very good..

Overall Score





6/10







Orange Book Value Not Available

IMAGES







Ordered by: Kalyan | Inspected date: 2019-04-19

Order Id: 63672

Overall Score



6/10



Orange Book Value Not Available

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.