

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 68748

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :  
Natasha

Inspection Date :  
2019-05-04

Location :  
JAIPUR

7/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 109 does not need attention
- ✓ 1 Owner , 15 Years Vehicle Age
- ✓ No Accidental History

Inspected By



VICKY KUMAR

- ✓ Verified Technician
- 145+ vehicle inspected
- 1+ years experience

## Maruti Suzuki Alto LXI, 2004



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	NOT SHOWN
MODEL	ALTO	REGISTRATION NO.	RJ148C4311
MFG. DATE	2004-01-01	VIN/CHASSIS NUMBER	NOT SHOWN
TRIM	LXI	ODOMETER READING	000000
COLOR	SILVER	INSURANCE EXPIRY	2018-8-15
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**69,306**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 22,000



Ordered by: Natasha | Inspected date: 2019-05-04

Order Id: 68748

Overall Score 7/10



69,306

## INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	8		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	9		0
NAVIGATION (NO)	10		0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	7		0
SPEAKERS & MUSIC SYSTEM	1	MISSING	2000
CENTRAL LOCK	0	NOT FITTING	0
ODOMETER	1	NOT WORKING	2000

## IMAGES



Ordered by: Natasha | Inspected date: 2019-05-04

Order Id: 68748

Overall Score  **7/10**



**69,306**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
IGNITION SYSTEM	1	MISSING	0
TRANSMISSION ENGAGE	1	NOT WORKING	2000

## IMAGES




## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH APRON	7	NOT OPENING	0
RADIATOR	6	NOT OPENING	0
WIRING	7	NOT OPENING	0
BATTERY	6	NOT OPENING	0
BRAKE FLUID LEVEL	7	NOT OPENING	0
ENGINE OIL	6	NOT OPENING	0
COOLANT LEVEL	7	NOT OPENING	0
BRAKE & COOLANT HOSE PIPES	7	NOT OPENING	0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0
LH APRON	1	NOT OPENING	500

 IMAGES



 NEED ATTENTION 



Ordered by: Natasha | Inspected date: 2019-05-04

Order Id: 68748

Overall Score  **7/10**



**69,306**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
GRILLE	8		0
TURN SIGNAL	7		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	7		0
LH FENDER	8		0
LH FRONT DOOR	7		0
LH REAR DOOR	8		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	8		0
FUEL LID	7		0
REAR WINDSHIELD	8		0
REAR BUMPER	7		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	8		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	6		0
LICENSE PLATE	4	FRONT	1000

Ordered by: Natasha | Inspected date: 2019-05-04

Order Id: 68748

Overall Score



7/10



69,306



## EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	3	BROKEN	2000
HEAD LIGHTS	2	NOT CLEAR	2000
FOG LAMPS	0	NOT FITTING	0
HOOD	2	NOT OPENING	500
PAINT CONDITION	2	FAIR	10000



## IMAGES





 **NEED ATTENTION** 



 **DESCRIPTION**

average



Ordered by: Natasha | Inspected date: 2019-05-04

Order Id: 68748

Overall Score



7/10



69,306

IMAGES





Ordered by: Natasha | Inspected date: 2019-05-04

Order Id: 68748

Overall Score



7/10



69,306

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.