



ECO INSPECTION CERTIFICATE

Premium

Order ID : 69113

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Madan	Inspection Date : 2019-05-01	Location : DELHI	 Inspected By  Verified Technician 339+ vehicle inspected 1+ years experience Hemant Kumar
-----------------------	---------------------------------	---------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 116 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

Tata Manza Aura Abs Quadrajt Bs-iv, 2012



VEHICLE INFORMATION

MAKE	TATA	ENGINE NUMBER	0243317
MODEL	MANZA	REGISTRATION NO.	DL8CX9122
MFG. DATE	2012-05-01	VIN/CHASSIS NUMBER	D08131
TRIM	AURA ABS QUADRAJET BS-IV	ODOMETER READING	71029
COLOR	T WINE	INSURANCE EXPIRY	2019-5-1
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






2,13,526




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 16,900



Ordered by: Madan | Inspected date: 2019-05-01

Order Id: 69113

Overall Score



7/10



2,13,526



INTERIOR






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	8	GOOD	0
HAZARD LIGHT	8	GOOD	0



IMAGES





TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	6	FAIR CONDITION	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES






WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0
SPARE TYRE (YES)	3	WEAK NEED TO CHANGE	5000

 IMAGES



 NEED ATTENTION 



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Madan | Inspected date: 2019-05-01

Order Id: 69113

Overall Score  **7/10**



2,13,526

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	6	FAIR CONDITION MINOR SCRATCHES	300
LH FRONT DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	6	FAIR CONDITION MINOR SCRATCHES	500
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	6	FAIR CONDITION MINOR SCRATCHES	300
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	6	FAIR CONDITION MINOR SCRATCHES	300
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	GOOD	0

ROOF (REGULAR)

7

GOOD

0

Ordered by: Madan | Inspected date: 2019-05-01

Order Id: 69113

Overall Score **7/10**




2,13,526



EXTERIOR (CONTINUED)

6/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	7	GOOD	0
FRONT BUMPER	5	SCRATCHES AND SOME PART BROKEN NEED TO REPAIR	3500
FOG LAMPS	0	NOT WORKING NEED TO CHANGE	2000
LH REAR DOOR	4	SCRATCHES NEED TO PAINT	3000
LH QUARTER PANEL	4	SCRATCHES NEED TO PAINT	2000

IMAGES





NEED ATTENTION ⚠️



DOCUMENTS



DESCRIPTION

fog lamp is not working left hand rear door scratches minor scratches in body

Ordered by: Madan | Inspected date: 2019-05-01

Order Id: 69113

Overall Score










7/10



2,13,526

IMAGES





Ordered by: Madan | Inspected date: 2019-05-01

Order Id: 69113

Overall Score



7/10



2,13,526

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.