

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 69332

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ankush	Inspection Date : 2019-05-06	Location : AMRITSAR	Inspected By  Jagbir Singh
------------------------	---------------------------------	------------------------	----------------------------------

## 8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 1 Owner , 10 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**  
31+ vehicle inspected  
1+ years experience

## Fiat Linea ACTIVE 1.3L ADVANCED MULTIJET DIESEL, 2009



### VEHICLE INFORMATION

MAKE	FIAT	ENGINE NUMBER	11325
MODEL	LINEA	REGISTRATION NO.	PB02BE2299
MFG. DATE	2009-01-01	VIN/CHASSIS NUMBER	46BOZ
TRIM	ACTIVE 1.3L ADVANCED MULTIJET DIESEL	ODOMETER READING	89909
COLOR	GREY	INSURANCE EXPIRY	2018-8-14
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	9,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,15,143**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 7,000



Ordered by: Ankush | Inspected date: 2019-05-06

Order Id: 69332

Overall Score



8/10



2,15,143



## INTERIOR






8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	9		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	9		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	9		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES - FRONT ONLY)	8		0
HAZARD LIGHT	8		0



## IMAGES



Ordered by: Ankush | Inspected date: 2019-05-06

Order Id: 69332

Overall Score  **8/10**




**2,15,143**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	9		0
ENGINE NOISE	8		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	9		0
CRUISE CONTROL (YES)	8		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (YES)	9		0

## IMAGES



## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD

 8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	9		0
RADIATOR	8		0
WIRING	8		0
BATTERY	9		0
BRAKE FLUID LEVEL	9		0
ENGINE OIL	7		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	9		0
EXHAUST SYSTEM	8		0

 IMAGES





Ordered by: Ankush | Inspected date: 2019-05-06

Order Id: 69332

Overall Score  **8/10**



**2,15,143**

 **EXTERIOR**

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	8		0
HEAD LIGHTS	9		0
GRILLE	8		0
TURN SIGNAL	9		0
FOG LAMPS	8		0
HOOD	9		0
PILLAR	9		0
FRONT WINDSHIELD	9		0
SIDE VIEW MIRRORS	8		0
LH FENDER	9		0
LH FRONT DOOR	8		0
LH REAR DOOR	9		0
LH RUNNING BOARD	9		0
LH QUARTER PANEL	7		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	8		0
RH REAR DOOR	9		0
RH FRONT DOOR	8		0

Ordered by: Ankush | Inspected date: 2019-05-06

Order Id: 69332

Overall Score



8/10



2,15,143



## EXTERIOR (CONTINUED)




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	9		0
BODY RUST	8		0
ROOF (REGULAR)	9		0
REAR BUMPER	2	BROKEN	2000
PAINT CONDITION	3	SCRACH	5000



## IMAGES






**NEED ATTENTION**



**DOCUMENTS**



**DESCRIPTION**





Ordered by: Ankush | Inspected date: 2019-05-06

Order Id: 69332

Overall Score























8/10



2,15,143

IMAGES





Ordered by: Ankush | Inspected date: 2019-05-06

Order Id: 69332

Overall Score



8/10



2,15,143

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.