



# ECO INSPECTION CERTIFICATE

Premium

Order ID : 71894

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ajay	Inspection Date : 2019-05-10	Location : 15 SEC	 Inspected By   <b>Verified Technician</b> 217+ vehicle inspected 1+ years experience  Pankaj Panwar
----------------------	---------------------------------	----------------------	--

**7/10**

**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 2 Owners , 11 Years Vehicle Age
- ✓ No Accidental History







## Hyundai Accent GLE, 2008



### VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	210810
MODEL	ACCENT	REGISTRATION NO.	DL3CAL7652
MFG. DATE	2008-07-01	VIN/CHASSIS NUMBER	210590
TRIM	GLE	ODOMETER READING	107542
COLOR	MIDNIGHT GREY	INSURANCE EXPIRY	2020-3-18
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	5,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






**1,00,186**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 19,000



Ordered by: ajay | Inspected date: 2019-05-10

Order Id: 71894

Overall Score  **7/10**




**1,00,186**

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	0

## IMAGES



Ordered by: ajay | Inspected date: 2019-05-10

Order Id: 71894

Overall Score  **7/10**



**1,00,186**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES



## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	7	MAXIMUM	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: ajay | Inspected date: 2019-05-10

Order Id: 71894

Overall Score  **7/10**



**1,00,186**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
HEAD LIGHTS	6	FAIR CONDITION AND WORKING PROPERLY	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	6	MINOR SCRATCHES	500
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH FRONT DOOR	6	MINOR SCRATCHES	500
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
FRONT BUMPER	5	NEED TO BE REAPING	2500
FOG LAMPS	0	NOT AVAILABLE	0
LH FENDER	5	MINOR SCRATCHES AND NEED TO BE REAPING	2500
LH REAR DOOR	5	MINOR SCRATCHES AND NEED TO BE REAPING	500



Ordered by: ajay | Inspected date: 2019-05-10

Order Id: 71894

Overall Score  **7/10**



**1,00,186**


## EXTERIOR (CONTINUED)

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
REAR BUMPER	5	NEED TO BE REAPING	2500
TAIL LIGHT	4	FAIR CONDITION NEEDS TO BE CHANG BOTH	3500
RH RUNNING BOARD	5	NEED TO BE REAPING	500
RH REAR DOOR	5	NEED TO BE REAPING	3500
RH FENDER	5	NEED TO BE REAPING	2500

## IMAGES






**NEED ATTENTION**



**DOCUMENTS**



**DESCRIPTION**

minor scratches and dent



Ordered by: ajay | Inspected date: 2019-05-10

Order Id: 71894

Overall Score



















7/10



1,00,186

 IMAGES





Ordered by: ajay | Inspected date: 2019-05-10

Order Id: 71894

Overall Score



7/10



1,00,186

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.