

ECO INSPECTION CERTIFICATE

Premium

Order ID : 75209

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Niranjan

Inspection Date :
2019-05-22

Location :
THANE WEST

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 113 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Gaurav
Phodkar

- ✓ Verified Technician
- 179+ vehicle inspected
- 1+ years experience










Chevrolet Aveo 1.4 CNG, 2011



VEHICLE INFORMATION

MAKE	CHEVROLET	ENGINE NUMBER	
MODEL	AVEO	REGISTRATION NO.	MH04EX6278
MFG. DATE	05/2011	VIN/CHASSIS NUMBER	MA6TFDE4BBH028191
TRIM	1.4 CNG	ODOMETER READING	59598
COLOR	S SILVER	INSURANCE EXPIRY	2019-8-8
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	YES








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,79,572




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 60%;"></div>	6 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 9,500



Ordered by: Niranjana | Inspected date: 2019-05-22

Order Id: 75209

Overall Score **6/10**




1,79,572


INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION	0
DOOR HINGES	6	ACCEPTABLE	0
CARPET & FLOOR MAT	6	ACCEPTABLE CONDITION	0
SEAT & SEAT BELT	6	GOOD WORKING	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD WORKING CONDITION	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	GOOD WORKING	0
HANDBRAKE	6	WORKING PROPERLY	0
PEDALS	6	GOOD WORKING	0
CENTRAL LOCK	6	WORKING GOOD	0
A/C VENTS & HEATER	6	GOOD COOLING	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD WORKING	0
POWER WINDOWS (YES)	6	WORKING GOOD	0
HAZARD LIGHT	6	WORKING GOOD	0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	0

IMAGES






TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	SMOOTHLY WORKING	0
BRAKE PERFORMANCE	6	GOOD WORKING	0
CLUTCH PERFORMANCE	6	WORKING GOOD	0
ENGINE NOISE	6	NORMAL NOISE	0
IGNITION SYSTEM	6	PROPERLY WORKING	0
SUSPENSION PERFORMANCE	6	GOOD SUSPENSION	0
SUSPENSION FRONT SHOCKS	6	ABSORBING GOOD ROAD SOCKS	0
SUSPENSION REAR SHOCKS	6	ABSORBING GOOD ROAD SOCKS	0
TRANSMISSION ENGAGE	6	SMOOTH GEAR ENGAGEMENT	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	6	GOOD WORKING	0
REAR VIEW CAMERA (YES)	6	GOOD WORKING	0



IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NORMAL WEAR AND TEAR	0

SPARE TYRE (YES)	6	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD CONDITION	0

IMAGES










HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	ACCEPTABLE CONDITION	0
RH APRON	6	ACCEPTABLE CONDITION	0
RADIATOR	6	GOOD WORKING	0
WIRING	6	ACCEPTABLE CONDITION	0
BATTERY	6	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM LEVEL	0
ENGINE OIL	6	GOOD VISCOSITY	0
COOLANT LEVEL	6	MORE THAN AVERAGE LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	GOOD CONDITION	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	GOOD WORKING	0

IMAGES



Ordered by: Niranjana | Inspected date: 2019-05-22

Order Id: 75209

Overall Score  **6/10**



1,79,572

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD CONDITION	0
HEAD LIGHTS	6	GOOD WORKING	0
GRILLE	6	ACCEPTABLE	0
TURN SIGNAL	6	GOOD WORKING	0
HOOD	6	GOOD CONDITION	0
PILLAR	6	GOOD CONDITION	0
FRONT WINDSHIELD	6	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	6	GOOD CONDITION	0
LH FENDER	6	GOOD CONDITION	0
LH RUNNING BOARD	6	GOOD CONDITION	0
FUEL LID	6	GOOD CONDITION	0
REAR WINDSHIELD	6	CLEAR VISIBILITY	0
TAIL LIGHT	6	GOOD WORKING	0
TRUNK LID/TAIL GATE	6	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	NORMAL SPACE	0
RH QUARTER PANEL	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION	0
RH FRONT DOOR	6	GOOD CONDITION	0
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	NO RUST FOUND	0
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD CONDITION	0
FRONT BUMPER	5	MINOR SCRATCHES FOUND	1500
FOG LAMPS	0	NOT AVAILABLE	0

Ordered by: Niranjan | Inspected date: 2019-05-22

Order Id: 75209

Overall Score



6/10



1,79,572



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH FRONT DOOR	5	MINOR DENT FOUND	1500
LH REAR DOOR	5	MINOR SCRATCHES FOUND	1500
LH QUARTER PANEL	5	MINOR SCRATCHES FOUND	2000
REAR BUMPER	5	NEED TO PAINT	2000
RH RUNNING BOARD	5	MINOR SCRATCH FOUND	1000





IMAGES








 **NEED ATTENTION** 





DOCUMENTS



DESCRIPTION

good condition car

Ordered by: Niranjan | Inspected date: 2019-05-22

Order Id: 75209

Overall Score



6/10



















1,79,572

IMAGES







Ordered by: Niranjan | Inspected date: 2019-05-22

Order Id: 75209

Overall Score



6/10



1,79,572

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.