

ECO INSPECTION CERTIFICATE

Premium

Order ID : 75681

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Gautam

Inspection Date :
2019-05-25

Location :
SEC 56

7/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 110 does not need attention
- ✓ 3 Owners , 14 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Manoj Kumar

- ✓ Verified Technician
- 716+ vehicle inspected
- 1+ years experience

Maruti Suzuki Esteem VXi BS II, 2005



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	179604
MODEL	ESTEEM	REGISTRATION NO.	MP09HE2387
MFG. DATE	02/2005	VIN/CHASSIS NUMBER	421909
TRIM	VXi BS II	ODOMETER READING	27963
COLOR	SILVER	INSURANCE EXPIRY	2019-5-25
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	18,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

55,622




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior		7 / 10
 Wheel		7 / 10
 Test Drive		8 / 10
 Exterior		6 / 10
 Hood		7 / 10

TOTAL ESTIMATE SPEND 25,300



Ordered by: Gautam | Inspected date: 2019-05-25

Order Id: 75681

Overall Score



7/10



55,622



INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA.	0



IMAGES



Ordered by: Gautam | Inspected date: 2019-05-25

Order Id: 75681

Overall Score



7/10



55,622



TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

IMAGES




HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

IMAGES



Ordered by: Gautam | Inspected date: 2019-05-25

Order Id: 75681

Overall Score



7/10



55,622



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	6	RH SIDE FOG LAMP MINOR CRACK	300
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	6	MINOR SCRATCHES AND DENT	400
LH REAR DOOR	6	MINOR PAINT REMOVE	500
LH QUARTER PANEL	6	MINOR SCRATCHES AND DENT	300
FUEL LID	7		0
REAR WINDSHIELD	7		0
TRUNK LID/TAIL GATE	6	MINOR DENT	300
LUGGAGE COMPARTMENT LIGHT	7		0
RH RUNNING BOARD	7		0
ROOF (REGULAR)	6	MINOR DENT	500
PAINT CONDITION	7	CAR FULL PAINTED	0
FRONT BUMPER	4	NEED TO REPAIR	2000
LH FRONT DOOR	4	NEED TO REPAIR	2500
LH RUNNING BOARD	4	NEED TO REPAIR	2000
REAR BUMPER	4	NEED TO REPAIR	2000
		LH SIDE TAIL LIGHT MINOR	

TAIL LIGHT	3	LEFT SIDE TAIL LIGHT MIRROR CRACK	1500
------------	---	--------------------------------------	------

Ordered by: Gautam | Inspected date: 2019-05-25

Order Id: 75681

Overall Score

7/10



55,622



EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH QUARTER PANEL	4	NEED TO REPAIR	1500
RH REAR DOOR	3	NEED TO REPAIR	2500
RH FRONT DOOR	4	NEED TO REPAIR	2500
RH FENDER	3	NEED TO REPAIR	1500
BODY RUST	3	BODY RUST	5000






IMAGES





NEED ATTENTION



DOCUMENTS



DESCRIPTION

odometer not working car fully painted seat covers cracking body rust minor scratches and minor dent

Ordered by: Gautam | Inspected date: 2019-05-25

Order Id: 75681

Overall Score













7/10



55,622

IMAGES





Ordered by: Gautam | Inspected date: 2019-05-25

Order Id: 75681

Overall Score



7/10



55,622



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.