

ECO INSPECTION CERTIFICATE

Premium

Order ID : 77829

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Puneet	Inspection Date : 2019-05-27	Location : FARIDABAD	Inspected By Dev Rajput ✓ Verified Technician 73+ vehicle inspected 1+ years experience
------------------------	---------------------------------	-------------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

Skoda Rapid AMBITION 1.6 TDI CR MT PLUS, 2013



VEHICLE INFORMATION			
MAKE	SKODA	ENGINE NUMBER	28101
MODEL	RAPID	REGISTRATION NO.	HR51AV2252
MFG. DATE	12/2012	VIN/CHASSIS NUMBER	32866
TRIM	AMBITION 1.6 TDI CR MT PLUS	ODOMETER READING	119501
COLOR	F RED	INSURANCE EXPIRY	2020-3-27
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

3,22,886

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 2,000	
Interior	<div style="width: 70%;"></div> 7 / 10	Interior	0
Wheel	<div style="width: 70%;"></div> 7 / 10	Wheel	0
Test Drive	<div style="width: 80%;"></div> 8 / 10	Test Drive	0
Exterior	<div style="width: 70%;"></div> 7 / 10	Exterior	2,000
Hood	<div style="width: 70%;"></div> 7 / 10	Hood	0

Ordered by: puneet | Inspected date: 2019-05-27

Order Id: 77829

Overall Score **7/10**



3,22,886

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
STEERING-MOUNTED CONTROLS	0	NA	0

IMAGES



Ordered by: puneet | Inspected date: 2019-05-27

Order Id: 77829

Overall Score **7/10**



3,22,886

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: puneet | Inspected date: 2019-05-27

Order Id: 77829

Overall Score  **7/10**



3,22,886

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0

Ordered by: puneet | Inspected date: 2019-05-27

Order Id: 77829

Overall Score **7/10**



3,22,886





EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	8	GOOD	0
TAIL LIGHT	3	RIGHT SIDE BROKEN TAIL LIGHT	2000
LUGGAGE COMPARTMENT LIGHT	0	NA	0

IMAGES








NEED ATTENTION



DOCUMENTS



DESCRIPTION

good condition vehicle

Ordered by: puneet | Inspected date: 2019-05-27

Order Id: 77829

Overall Score




7/10



3,22,886

IMAGES





Ordered by: puneet | Inspected date: 2019-05-27

Order Id: 77829

Overall Score



7/10



3,22,886

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.