


ECO INSPECTION CERTIFICATE

Premium

Order ID : 77836

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rohit	Inspection Date : 2019-05-30	Location : JAIPUR	Inspected By  VICKY KUMAR
-----------------------	---------------------------------	----------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **111** does not need attention
- ✔ **2** Owners , **18** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**
220+ vehicle inspected
1+ years experience

Maruti Suzuki 800 STD BS II, 2001



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	99085
MODEL	800	REGISTRATION NO.	RJ146C2065
MFG. DATE	01/2001	VIN/CHASSIS NUMBER	87093
TRIM	STD BS II	ODOMETER READING	0000
COLOR	WHITE	INSURANCE EXPIRY	2019-1-14
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	6,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

23,784




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Wheel	<div style="width: 80%; background-color: green;"></div>	8 / 10
Test Drive	<div style="width: 70%; background-color: green;"></div>	7 / 10
Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 5,500



Ordered by: Rohit | Inspected date: 2019-05-30

Order Id: 77836

Overall Score **7/10**



23,784

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	7	KEY IS MISSING	0
HORN	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	7		0
SPEAKERS & MUSIC SYSTEM	0	KEY MISSING	0
CENTRAL LOCK	0	NOT FITTING	0
A/C VENTS & HEATER	0	NOT FITTING	0
CUP HOLDERS	0	NOT FITTING	0

IMAGES



Ordered by: Rohit | Inspected date: 2019-05-30

Order Id: 77836

Overall Score **7/10**



23,784

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
ENGINE NOISE	0	KEYS ARE MISSING	0
IGNITION SYSTEM	0	NOT FITTING	0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	KEY IS MISSING	0
RH APRON	6	KEY MISSING	0
RADIATOR	8		0
WIRING	7	KEY MISSING	0
BATTERY	7	KEY MISSING	0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	8		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	8		0

 IMAGES





www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Rohit | Inspected date: 2019-05-30

Order Id: 77836

Overall Score  **7/10**



23,784

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	8		0
HEAD LIGHTS	7		0
GRILLE	8		0
TURN SIGNAL	8		0
PILLAR	7		0
FRONT WINDSHIELD	8		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	8		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	8		0
REAR WINDSHIELD	7		0
REAR BUMPER	8		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	6		0
RH FRONT DOOR	7		0
RH FENDER	8		0
BODY RUST	7		0
ROOF (REGULAR)	8		0

Ordered by: Rohit | Inspected date: 2019-05-30

Order Id: 77836

Overall Score **7/10**



23,784

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	7		0
FOG LAMPS	0	NOT FITTING	0
HOOD	3	DENT	4000
SIDE VIEW MIRRORS	3	LEFT MISSING	1000
RH REAR DOOR	3	BROKEN	500

IMAGES





NEED ATTENTION



DOCUMENTS



DESCRIPTION

fair

Ordered by: Rohit | Inspected date: 2019-05-30

Order Id: 77836

Overall Score



7/10



23,784

IMAGES





Ordered by: Rohit | Inspected date: 2019-05-30

Order Id: 77836

Overall Score



7/10



23,784

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.