


ECO INSPECTION CERTIFICATE


Premium

Order ID : 81481

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vizag	Inspection Date : 2019-06-08	Location : VISAKHAPATNAM	Inspected By  NAMBALA VENKATESWARA RAO
-----------------------	---------------------------------	-----------------------------	---

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 2 Owners , 10 Years Vehicle Age
- ✓ No Accidental History

✓ Verified Technician
 2+ vehicle inspected
 1+ years experience




Audi A4 2.0 TDI, 2009



VEHICLE INFORMATION

MAKE	AUDI	ENGINE NUMBER	
MODEL	A4	REGISTRATION NO.	AP09BS4545
MFG. DATE	07/2008	VIN/CHASSIS NUMBER	WAUZG88K89A068414
TRIM	2.0 TDI	ODOMETER READING	89519
COLOR	BRILLIANT RED	INSURANCE EXPIRY	2019-11-12
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	1,500	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	NO (3RD PARTY)	 BANK NOC	YES













Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

9,08,610




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior		6 / 10
 Wheel		6 / 10
 Test Drive		6 / 10
 Exterior		6 / 10
 Hood		6 / 10

TOTAL ESTIMATE SPEND 4,000



Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score



6/10



9,08,610



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
STEERING-MOUNTED CONTROLS	6		0
PEDALS	6		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	6		0
NAVIGATION (YES)	6		0
ODOMETER	6		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	6		0



IMAGES



Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score



6/10



9,08,610



TEST DRIVE





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (YES)	6		0
REAR PARKING SENSORS (YES)	6		0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score



6/10



9,08,610

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0

Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score **6/10**






9,08,610

EXTERIOR (CONTINUED)


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6		0
ROOF (SUN ROOF)	6		0
PAINT CONDITION	6		0
FRONT BUMPER	5	SCRATCHES ARE THERE	2500
SIDE VIEW MIRRORS	5	SCRATCHES ARE THERE ON MIRRORS	1500

IMAGES



NEED ATTENTION ⚠



Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score



6/10



9,08,610

DOCUMENTS



DESCRIPTION

dunts and scratches are there in some place and near bumper caps are open and dunts on mud geat

Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score




6/10



9,08,610

 IMAGES



Cubic Capacity	1968
Maker's Classification	AUDIM42.BTD
Wheel Base	2817 in all
Seating Capacity	5
Unladen Weight	1670
Color	BRIGHT RED
Year of Purchase	H D F C BANK LTD
No. of current transfers	2
Diagn. Valid upto	2001/2024
Tax	Rs.291350(Life Time)
Date of Registration	21/03/2009
Signature of the Owner	Add. Registering Authority RTA-VISAKHAPATNAM

Ordered by: Vizag | Inspected date: 2019-06-08

Order Id: 81481

Overall Score



6/10



9,08,610

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.