


ECO INSPECTION CERTIFICATE

Premium

Order ID : 113782

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Adnan	Inspection Date : 2019-10-01	Location : LUCKNOW	Inspected By  Vipin Bajpai
-----------------------	---------------------------------	-----------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **117** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

- ✔ **Verified Technician**
- 22+ vehicle inspected
- 1+ years experience







Maruti Suzuki Wagon R 1.0 Lxi Cng Opt, 2015



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	K10BN76193
MODEL	WAGON R 1.0	REGISTRATION NO.	UP17T8719
MFG. DATE	09/2015	VIN/CHASSIS NUMBER	MA3EWDE1S00951039
TRIM	LXI CNG OPT	ODOMETER READING	73002
COLOR	WHITE	INSURANCE EXPIRY	2019-11-21
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	CNG	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






3,09,646




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 1,500



Ordered by: Adnan | Inspected date: 2019-10-01

Order Id: 113782

Overall Score



7/10



3,09,646



INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	BOTH DOOR'S PANELS ARE IN AVERAGE CONDITION	0
DOOR HINGES	8	BOTH DOOR'S HINGES & LATCH ARE WORKING IN GOOD CONDITION	0
CARPET & FLOOR MAT	8	CARPET IS IN GOOD CONDITION	0
SEAT & SEAT BELT	8	SEATS/SEAT COVERS ARE IN GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	DASHBOARD/INSTRUMENT PANEL IS IN GOOD CONDITION	0
HORN	8	HORN SOUND IS IN GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	SPEAKER'S SOUND IS IN GOOD CONDITION	0
HANDBRAKE	8	HAND BRAKE IS IN GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	STEERING MOUNTED CONTROLS ARE WORKING IN GOOD CONDITION	0
PEDALS	8	ALL PEDAL'S BOOT IS IN GOOD CONDITION	0
CENTRAL LOCK	8	ALL DOOR'S LOCKS ARE WORKING IN GOOD CONDITION	0
A/C VENTS & HEATER	10	AC/HEATER IS WORKING AND COOLING/HEATING	0
CUP HOLDERS	8	CUP HOLDERS ARE IN GOOD CONDITION	0
ODOMETER	8	ODOMETER IS WORKING IN GOOD CONDITION	0
POWER WINDOWS (YES)	8	ALL POWER WINDOWS ARE WORKING IN GOOD CONDITION	0
HAZARD LIGHT	8	HAZARD LIGHT IS WORKING IN GOOD CONDITION	0




IN GOOD CONDITION

NAVIGATION (NO)

N/A

0

 IMAGES



Ordered by: Adnan | Inspected date: 2019-10-01

Order Id: 113782

Overall Score **7/10**




3,09,646

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	STEERING WORKING IS IN GOOD CONDITION	0
BRAKE PERFORMANCE	8	BRAKES ARE WORKING IN GOOD CONDITION	0
CLUTCH PERFORMANCE	8	CLUTCH IS WORKING IS IN GOOD CONDITION	0
ENGINE NOISE	8	NO ANY ABNORMAL NOISE IN ENGINE	0
IGNITION SYSTEM	6	IGNITION SYSTEM IS WORKING IN AVERAGE CONDITION.	0
SUSPENSION PERFORMANCE	6	SUSPENSION PERFORMANCE IS IN AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	FRONT SUSPENSION IS WORKING IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	8	REAR SUSPENSION IS WORKING IN GOOD CONDITION	0
TRANSMISSION ENGAGE	8	TRANSMISSION IS WORKING IN GOOD CONDITION	0
CRUISE CONTROL (NO)	N/A		0
REAR PARKING SENSORS (NO)	N/A		0
REAR VIEW CAMERA (NO)	N/A		0

IMAGES





INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	TIRES ARE IN AVERAGE CONDITION	0
SPARE TYRE (YES)	6	SPARE TYRE IS IN AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	8	MAJOR PROBLEM IN WHEEL ALIGNMENT.	0

 IMAGES

 HOOD


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	LH APRON IS IN AVERAGE CONDITION	0
RH APRON	6	RH APRON IS IN AVERAGE CONDITION	0
RADIATOR	8	RADIATOR IS IN GOOD CONDITION	0
WIRING	6	WIRING HARNESS IS IN AVERAGE CONDITION	0
BATTERY	8	BATTERY IS IN GOOD CONDITION	0
BRAKE FLUID LEVEL	8	BRAKE FLUID & LEVEL IS IN GOOD CONDITION	0
ENGINE OIL	8	ENGINE OIL IS IN GOOD CONDITION	0
COOLANT LEVEL	8	COOLANT LEVEL IS IN GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	8	ALL HOSES/PIPES IS IN GOOD CONDITION	0
UNDERCARRIAGE	8	UNDERCARRIAGE IS IN GOOD CONDITION	0
EXHAUST SYSTEM	6	EXHAUST GAS IS IN AVERAGE CONDITION	0

 IMAGES



Ordered by: Adnan | Inspected date: 2019-10-01

Order Id: 113782

Overall Score



7/10



3,09,646

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	LICENSE PLATE IS IN AVERAGE CONDITION.	0
FRONT BUMPER	6	FRONT BUMPER IS IN AVERAGE CONDITION	0
HEAD LIGHTS	6	HEAD LIGHTS ARE WORKING IN AVERAGE CONDITION	0
GRILLE	6	GRILLE IS IN AVERAGE CONDITION	0
TURN SIGNAL	6	INDICATOR IS WORKING IN AVERAGE CONDITION	0
FOG LAMPS	6	FOG LAMPS IS IN AVERAGE CONDITION	0
HOOD	6	HOOD IS IN AVERAGE CONDITION	0
PILLAR	8	LH PILLARS IS IN GOOD CONDITION	0
FRONT WINDSHIELD	6	FRONT WINDSHIELD IS IN AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	LH SIDE VIEW MIRROR/ASSY IS IN AVERAGE CONDITION	0
LH FENDER	8	LH FENDER IS IN GOOD CONDITION	0
LH FRONT DOOR	6	LH FRONT DOOR IS IN AVERAGE CONDITION	0
LH REAR DOOR	6	LH REAR DOOR IS IN AVERAGE CONDITION	0
LH RUNNING BOARD	6	LH RUNNING BOARD IS IN AVERAGE CONDITION	0
LH QUARTER PANEL	6	LH QUARTER PANEL IS IN AVERAGE CONDITION	0
FUEL LID	6	FUEL LID IS IN AVERAGE CONDITION	0
REAR WINDSHIELD	8	REAR WINDSHIELD IS IN GOOD CONDITION	0

REAR BUMPER	6	REAR BUMPER IS IN AVERAGE CONDITION	0
TAIL LIGHT	8	TAIL LIGHT IS WORKING IN GOOD CONDITION	0
TRUNK LID/TAIL GATE	6	TRUNK LID IS IN AVERAGE CONDITION	0
LUGGAGE COMPARTMENT LIGHT	8	LUGGAGE COMPARTMENT LIGHT IS WORKING IN GOOD CONDITION	0
RH QUARTER PANEL	8	RH QUARTER PANEL IS IN GOOD CONDITION	0
RH RUNNING BOARD	6	RH RUNNING BOARD IS IN AVERAGE CONDITION	0
RH REAR DOOR	6	RH REAR DOOR IS IN AVERAGE CONDITION	0

Ordered by: Adnan | Inspected date: 2019-10-01

Order Id: 113782

Overall Score **7/10**



3,09,646

EXTERIOR (CONTINUED)

6/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	RH FRONT DOOR IS IN AVERAGE CONDITION	1500
RH FENDER	6	RH FENDER IS IN AVERAGE CONDITION	0
BODY RUST	6	BODY RUST 25%-MINOR	0
ROOF (REGULAR)	6	ROOF IS IN AVERAGE CONDITION	0
PAINT CONDITION	6	PAINT IS IN AVERAGE CONDITION	0

IMAGES





 DOCUMENTS



 DESCRIPTION

Good

Ordered by: Adnan | Inspected date: 2019-10-01

Order Id: 113782

Overall Score



7/10



3,09,646

IMAGES (55)





Ordered by: Adnan | Inspected date: 2019-10-01

Order Id: 113782

Overall Score



7/10



3,09,646

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.