


ECO INSPECTION CERTIFICATE

Premium

Order ID : 115113

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ishita	Inspection Date : 2019-10-11	Location : LUCKNOW	Inspected By  Hemant Pandey
------------------------	---------------------------------	-----------------------	--

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **6** Years Vehicle Age
- ✔ No Accidental History










✔ **Verified Technician**


14+ vehicle inspected
1+ years experience

Mercedes-Benz C-Class C220 D, 2013



VEHICLE INFORMATION			
MAKE	MERCEDES-BENZ	ENGINE NUMBER	6519113170
MODEL	C-CLASS	REGISTRATION NO.	UP78DF0555
MFG. DATE	07/2013	VIN/CHASSIS NUMBER	WDD2040026L069804
TRIM	C220 D	ODOMETER READING	76236
COLOR	POLAR WHITE	INSURANCE EXPIRY	2019-1-13
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

Orange Book Value Not Available



ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%; height: 10px; background-color: green; border: 1px solid gray;"></div>	7 / 10
 Wheel	<div style="width: 70%; height: 10px; background-color: green; border: 1px solid gray;"></div>	7 / 10
 Test Drive	<div style="width: 60%; height: 10px; background-color: yellow; border: 1px solid gray;"></div>	6 / 10
 Exterior	<div style="width: 60%; height: 10px; background-color: yellow; border: 1px solid gray;"></div>	6 / 10
 Hood	<div style="width: 70%; height: 10px; background-color: green; border: 1px solid gray;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0


0


0


0


0


0

 Interior

 Wheel

 Test Drive

 Exterior

 Hood

Ordered by: Ishita | Inspected date: 2019-10-11

Order Id: 115113

Overall Score



6/10



Orange Book Value Not Available



INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	BOTH DOOR'S PANELS ARE IN AVERAGE CONDITION	0
DOOR HINGES	6	BOTH DOOR'S HINGES & LATCH ARE WORKING IN AVERAGE CONDITION	0
CARPET & FLOOR MAT	6	CARPET IS IN AVERAGE CONDITION	0
SEAT & SEAT BELT	6	SEATS/SEAT COVERS ARE IN AVERAGE CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	DASHBOARD/INSTRUMENT PANEL IS IN AVERAGE CONDITION	0
HORN	6	HORN SOUND IS IN AVERAGE CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	SPEAKER'S SOUND IS IN GOOD CONDITION	0
HANDBRAKE	8	HAND BRAKE IS IN GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	STEERING MOUNTED CONTROLS ARE WORKING IN GOOD CONDITION	0
PEDALS	8	ALL PEDAL'S BOOT IS IN GOOD CONDITION	0
CENTRAL LOCK	8	ALL DOOR'S LOCKS ARE WORKING IN GOOD CONDITION	0
A/C VENTS & HEATER	10	AC/HEATER IS WORKING AND COOLING/HEATING	0
CUP HOLDERS	8	CUP HOLDERS ARE IN GOOD CONDITION	0
NAVIGATION (YES)	8	NAVIGATION SYSTEM IS WORKING IN GOOD CONDITION	0
ODOMETER	8	ODOMETER IS WORKING IN GOOD CONDITION	0
POWER WINDOWS (YES)	8	ALL POWER WINDOWS ARE WORKING IN GOOD CONDITION	0

POWER WINDOWS (YES)	8	WORKING IN GOOD CONDITION	0
HAZARD LIGHT	8	HAZARD LIGHT IS WORKING IN GOOD CONDITION	0

IMAGES



Ordered by: Ishita | Inspected date: 2019-10-11

Order Id: 115113

Overall Score



6/10



Orange Book Value Not Available



TEST DRIVE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	STEERING WORKING IS IN AVERAGE CONDITION	0
BRAKE PERFORMANCE	6	BRAKES ARE WORKING IN AVERAGE CONDITION	0
CLUTCH PERFORMANCE	6	CLUTCH IS WORKING IN AVERAGE CONDITION	0
ENGINE NOISE	8	NO ANY ABNORMAL NOISE IN ENGINE	0
IGNITION SYSTEM	8	IGNITION SYSTEM IS WORKING IN GOOD CONDITION	0
SUSPENSION PERFORMANCE	6	SUSPENSION PERFORMANCE IS IN AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	FRONT SUSPENSION IS WORKING IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	REAR SUSPENSION IS WORKING IN AVERAGE CONDITION	0
TRANSMISSION ENGAGE	6	TRANSMISSION IS WORKING IN AVERAGE CONDITION	0
CRUISE CONTROL (YES)	6	CRUISE CONTROL IS WORKING IN AVERAGE CONDITION	0
REAR PARKING SENSORS (YES)	6	REAR PARKING SENSOR IS WORKING IN AVERAGE CONDITION	0
REAR VIEW CAMERA (NO)	N/A		0




IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	TIRES ARE IN AVERAGE CONDITION	0
SPARE TYRE (YES)	8	SPARE TYRE IS IN GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	8	MAJOR PROBLEM IN WHEEL ALIGNMENT.	0

 IMAGES

 HOOD


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	LH APRON IS IN AVERAGE CONDITION	0
RH APRON	6	RH APRON IS IN AVERAGE CONDITION	0
RADIATOR	8	RADIATOR IS IN GOOD CONDITION	0
WIRING	8	WIRING HARNESS IS IN GOOD CONDITION	0
BATTERY	8	BATTERY IS IN GOOD CONDITION	0
BRAKE FLUID LEVEL	6	BRAKE FLUID IS IN AVERAGE CONDITION	0
ENGINE OIL	6	ENGINE OIL IS IN AVERAGE CONDITION	0
COOLANT LEVEL	6	COOLANT LEVEL IS IN AVERAGE CONDITION	0
BRAKE & COOLANT HOSE PIPES	6	ALL HOSES/PIPES IS IN AVERAGE CONDITION	0
UNDERCARRIAGE	6	UNDERCARRIAGE IS IN AVERAGE CONDITION	0
EXHAUST SYSTEM	8	NORMAL SMOKE	0

 IMAGES



Ordered by: Ishita | Inspected date: 2019-10-11

Order Id: 115113

Overall Score



6/10



Orange Book Value Not Available



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	LICENSE PLATE IS IN GOOD CONDITION	0
FRONT BUMPER	6	FRONT BUMPER IS IN AVERAGE CONDITION	0
HEAD LIGHTS	8	HEAD LIGHTS ARE WORKING IN GOOD CONDITION	0
GRILLE	6	GRILLE IS IN AVERAGE CONDITION	0
TURN SIGNAL	8	INDICATOR IS WORKING IN GOOD CONDITION	0
FOG LAMPS	6	FOG LAMPS IS IN AVERAGE CONDITION	0
HOOD	6	HOOD IS IN AVERAGE CONDITION	0
PILLAR	6	LH PILLARS ARE IN AVERAGE CONDITION	0
FRONT WINDSHIELD	8	FRONT WINDSHIELD IS IN GOOD CONDITION	0
SIDE VIEW MIRRORS	6	LH SIDE VIEW MIRROR/ASSY IS IN AVERAGE CONDITION	0
LH FENDER	6	LH FENDER IS IN AVERAGE CONDITION	0
LH FRONT DOOR	6	LH FRONT DOOR IS IN AVERAGE CONDITION	0
LH REAR DOOR	6	LH REAR DOOR IS IN AVERAGE CONDITION	0
LH RUNNING BOARD	6	LH RUNNING BOARD IS IN AVERAGE CONDITION	0
LH QUARTER PANEL	6	LH QUARTER PANEL IS IN AVERAGE CONDITION	0
FUEL LID	6	FUEL LID IS IN AVERAGE CONDITION	0
REAR WINDSHIELD	8	REAR WINDSHIELD IS IN GOOD CONDITION	0

REAR BUMPER	6	REAR BUMPER IS IN AVERAGE CONDITION	0
TAIL LIGHT	8	TAIL LIGHT IS WORKING IN GOOD CONDITION	0
TRUNK LID/TAIL GATE	6	TRUNK LID IS IN AVERAGE CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	LUGGAGE COMPARTMENT LIGHT IS WORKING IN AVERAGE CONDITION	0
RH QUARTER PANEL	6	RH QUARTER PANEL IS IN AVERAGE CONDITION	0
RH RUNNING BOARD	6	RH RUNNING BOARD IS IN AVERAGE CONDITION	0
RH REAR DOOR	6	RH REAR DOOR IS IN AVERAGE CONDITION	0

Ordered by: Ishita | Inspected date: 2019-10-11

Order Id: 115113

Overall Score **6/10**



Orange Book Value Not Available





EXTERIOR (CONTINUED)

6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	RH FRONT DOOR IS IN AVERAGE CONDITION	0
RH FENDER	6	RH FENDER IS IN AVERAGE CONDITION	0
BODY RUST	6	BODY RUST 25%-MINOR	0
ROOF (SUN ROOF)	6	ROOF IS IN AVERAGE CONDITION	0
PAINT CONDITION	8	PAINT IS IN GOOD CONDITION	0

IMAGES





 DOCUMENTS



 DESCRIPTION

Good

Ordered by: Ishita | Inspected date: 2019-10-11

Order Id: 115113

Overall Score











6/10



Orange Book Value Not Available

IMAGES (53)





Ordered by: Ishita | Inspected date: 2019-10-11

Order Id: 115113

Overall Score



6/10



Orange Book Value Not Available

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.