

ECO INSPECTION CERTIFICATE

Premium

Order ID : 118316

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Qamar Yab

Inspection Date :
2019-10-29

Location :
LUCKNOW

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 115 does not need attention
- ✓ 2 Owners , 6 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Faraz Khan

- ✓ **Verified Technician**
- 84+ vehicle inspected
- 1+ years experience

Nissan Micra XI Diesel, 2013



VEHICLE INFORMATION

MAKE	NISSAN	ENGINE NUMBER	K8KAA22ED0
MODEL	MICRA	REGISTRATION NO.	UP32EX1749
MFG. DATE	01/2013	VIN/CHASSIS NUMBER	MDHFCUK13D1512044
TRIM	XL DIESEL	ODOMETER READING	90484
COLOR	WHITE	INSURANCE EXPIRY	2019-6-11
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,15,661




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 1,000



Ordered by: qamar yab | Inspected date: 2019-10-29

Order Id: 118316

Overall Score **8/10**



2,15,661

INTERIOR

8/10




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	BOTH DOOR'S PANELS ARE IN GOOD CONDITION	0
DOOR HINGES	8	BOTH DOOR'S HINGES & LATCH ARE WORKING IN GOOD CONDITION	0
CARPET & FLOOR MAT	8	CARPET IS IN GOOD CONDITION	0
SEAT & SEAT BELT	8	SEATS/SEAT COVERS ARE IN GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	DASHBOARD/INSTRUMENT PANEL IS IN GOOD CONDITION	0
HORN	8	HORN SOUND IS IN GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	SPEAKER'S SOUND IS IN GOOD CONDITION	0
HANDBRAKE	8	HAND BRAKE IS IN GOOD CONDITION	0
PEDALS	8	ALL PEDAL'S BOOT IS IN GOOD CONDITION	0
CENTRAL LOCK	8	ALL DOOR'S LOCKS ARE WORKING IN GOOD CONDITION	0
A/C VENTS & HEATER	10	AC/HEATER IS WORKING AND COOLING/HEATING	0
CUP HOLDERS	8	CUP HOLDERS ARE IN GOOD CONDITION	0
ODOMETER	8	ODOMETER IS WORKING IN GOOD CONDITION	0
POWER WINDOWS (YES)	8	ALL POWER WINDOWS ARE WORKING IN GOOD CONDITION.	0
HAZARD LIGHT	8	HAZARD LIGHT IS WORKING IN GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	N/A		0

NAVIGATION (NO)

N/A

0

 IMAGES



Ordered by: qamar yab | Inspected date: 2019-10-29

Order Id: 118316

Overall Score **8/10**





2,15,661

TEST DRIVE

8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	STEERING WORKING IS IN GOOD CONDITION	0
BRAKE PERFORMANCE	8	BRAKES ARE WORKING IN GOOD CONDITION	0
CLUTCH PERFORMANCE	8	CLUTCH IS WORKING IN GOOD CONDITION	0
ENGINE NOISE	8	NO SOMETIMES MINOR NOISE IN ENGINE.	0
IGNITION SYSTEM	8	IGNITION SYSTEM IS WORKING IN GOOD CONDITION.	0
SUSPENSION PERFORMANCE	8	SUSPENSION PERFORMANCE IS IN GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	8	FRONT SUSPENSION IS WORKING IN GOOD CONDITION	0
SUSPENSION REAR SHOCKS	8	REAR SUSPENSION IS WORKING IN GOOD CONDITION	0
TRANSMISSION ENGAGE	8	TRANSMISSION IS WORKING IN GOOD CONDITION	0
CRUISE CONTROL (NO)	N/A		0
REAR PARKING SENSORS (NO)	N/A		0
REAR VIEW CAMERA (YES)	4	REAR VIEW CAMERA/DISPLAY NOT WORKING PROPERLY	500

IMAGES



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	TIRES ARE IN GOOD CONDITION	0
SPARE TYRE (YES)	8	SPARE TYRE IS IN GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	8	WHEEL ALIGNMENT IS IN GOOD CONDITION.	0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	LH APRON IS IN GOOD CONDITION	0
RH APRON	8	RH APRON IS IN GOOD CONDITION	0
RADIATOR	8	RADIATOR IS IN GOOD CONDITION	0
WIRING	8	WIRING HARNESS IS IN GOOD CONDITION	0
BATTERY	8	BATTERY IS IN GOOD CONDITION	0
BRAKE FLUID LEVEL	8	BRAKE FLUID IS IN GOOD CONDITION	0
ENGINE OIL	8	ENGINE OIL IS IN GOOD CONDITION	0
COOLANT LEVEL	8	COOLANT LEVEL IS IN GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	8	ALL HOSES/PIPES IS IN GOOD CONDITION	0
UNDERCARRIAGE	8	UNDERCARRIAGE IS IN GOOD CONDITION	0
EXHAUST SYSTEM	8	EXHAUST GAS IS IN GOOD CONDITION	0

 IMAGES



Ordered by: qamar yab | Inspected date: 2019-10-29

Order Id: 118316

Overall Score  **8/10**



2,15,661

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	6	FRONT BUMPER IS IN AVERAGE CONDITION	0
HEAD LIGHTS	8	HEAD LIGHTS ARE WORKING IN GOOD CONDITION	0
GRILLE	8	GRILLE IS IN GOOD CONDITION	0
TURN SIGNAL	8	INDICATOR IS WORKING IN GOOD CONDITION	0
FOG LAMPS	8	FOG LAMPS IS IN GOOD CONDITION	0
HOOD	8	HOOD IS IN GOOD CONDITION	0
PILLAR	8	LH PILLARS ARE IN GOOD CONDITION	0
FRONT WINDSHIELD	8	FRONT WINDSHIELD IS IN GOOD CONDITION	0
SIDE VIEW MIRRORS	8	LH SIDE VIEW MIRROR/ASSY IS IN GOOD CONDITION	0
LH FENDER	8	LH FENDER IS IN GOOD CONDITION	0
LH FRONT DOOR	8	LH FRONT DOOR IS IN GOOD CONDITION	0
LH REAR DOOR	8	LH REAR DOOR IS IN GOOD CONDITION	0
LH RUNNING BOARD	8	LH RUNNING BOARD IS IN GOOD CONDITION	0
LH QUARTER PANEL	8	LH QUARTER PANEL IS IN GOOD CONDITION	0
FUEL LID	8	FUEL LID IS IN GOOD CONDITION	0
REAR WINDSHIELD	8	REAR WINDSHIELD IS IN GOOD CONDITION	0
REAR BUMPER	8	REAR BUMPER IS IN GOOD CONDITION	0

TAIL LIGHT	8	TAIL LIGHT IS WORKING IN GOOD CONDITION	0
TRUNK LID/TAIL GATE	8	TRUNK LID IS IN GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	8	LUGGAGE COMPARTMENT LIGHT IS WORKING IN GOOD CONDITION	0
RH QUARTER PANEL	8	RH QUARTER PANEL IS IN GOOD CONDITION	0
RH RUNNING BOARD	8	RH RUNNING BOARD IS IN GOOD CONDITION	0
RH REAR DOOR	8	RH REAR DOOR IS IN GOOD CONDITION	0
RH FRONT DOOR	8	RH FRONT DOOR IS IN GOOD CONDITION	0

Ordered by: qamar yab | Inspected date: 2019-10-29

Order Id: 118316

Overall Score **8/10**



2,15,661





EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	8	RH FENDER IS IN GOOD CONDITION	0
BODY RUST	6	BODY RUST 25%-MINOR	0
ROOF (REGULAR)	8	ROOF IS IN GOOD CONDITION	0
PAINT CONDITION	6	PAINT IS IN AVERAGE CONDITION	0
LICENSE PLATE	4	LICENSE PLATE MINOR BLURRED	500

IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

good

Overall Score









8/10



2,15,661

IMAGES (49)





Ordered by: qamar yab | Inspected date: 2019-10-29

Order Id: 118316

Overall Score



8/10



2,15,661

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.