

ECO INSPECTION REPORT


Premium

Order ID : 26511

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Shoab	Inspection Date : 2018-10-05	Valid Till : 2019-01-05
-----------------------	---------------------------------	----------------------------


8/10



Overall Score

- ✔ Evaluated across 5 segments
- ✔ Covered 121+ checkpoints
- ✔ 120 does not need attention
- ✔ 1 Owner , 6 Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

14+ vehicle inspected

1+ years experience

Sanmesh Latke

Tata Nano Cx, 2012



VEHICLE INFORMATION			
MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	NANO	REGISTRATION NO.	MH02CV2321
YEAR	2012	VIN/CHASIS NUMBER	MAT612227CKD31409
TRIM	CX	KMS RUN	7630
COLOR	RED	INSURANCE EXPIRY	2018-10-1
BODY TYPE	HATCHBACK	LOCATION	ANDHERI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	80,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Price for this vehicle comes to be:

81,798




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 10,000



Ordered by: Shoab | Inspected date: 2018-10-05

Order Id: 26511

Overall Score



8/10



81,798



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	OK	0
DOOR HINGES	8	OK	0
CARPET & FLOOR MAT	8	OK	0
SEAT & SEAT BELT	9	OK	0
DASHBOARD & INSTRUMENT PANEL	8	OK	0
HORN	6	NOT WORKING	1000
SPEAKERS & MUSIC SYSTEM	7	NOT APPLICABLE	0
HANDBRAKE	7	OK	0
STEERING-MOUNTED CONTROLS	8	OK	0
PEDALS	8	OK	0
CENTRAL LOCK	8	OK	0
A/C VENTS & HEATER	8	OK	0
CUP HOLDERS	8	OK	0
ODOMETER	7	NOT WORKING PROPERLY	3000
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	8	OK	0
NAVIGATION (NO)	0	NOT APPLICABLE	0



IMAGES



Ordered by: Shoab | Inspected date: 2018-10-05

Order Id: 26511

Overall Score



8/10



81,798



TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	OK	0
BRAKE PERFORMANCE	8	OK	0
CLUTCH PERFORMANCE	8	OK	0
ENGINE NOISE	8	OK	0
IGNITION SYSTEM	8	OK	0
SUSPENSION PERFORMANCE	8	OK	0
SUSPENSION FRONT SHOCKS	8	OK	0
SUSPENSION REAR SHOCKS	8	OK	0
TRANSMISSION ENGAGE	7	NOT WORKING	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	OK	0
SPARE TYRE (YES)	8	OK	0
WHEEL ASSEMBLY	8	OK	0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	OK	0
RH APRON	8	OK	0
RADIATOR	8	OK	0
WIRING	8	OK	0
BATTERY	9	OK	0
BRAKE FLUID LEVEL	8	OK	0
ENGINE OIL	9	OK	0
COOLANT LEVEL	8	OK	0
BRAKE & COOLANT HOSE PIPES	8	OK	0
UNDERCARRIAGE	8	OK	0
EXHAUST SYSTEM	8	OK	0

 IMAGES



Ordered by: Shoaib | Inspected date: 2018-10-05

Order Id: 26511

Overall Score



8/10



81,798

 EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	OK	0
FRONT BUMPER	8	OK	0
HEAD LIGHTS	8	OK	0
GRILLE	8	OK	0
TURN SIGNAL	8	OK	0
FOG LAMPS	8	NOT AVAILABLE	0
HOOD	8	OK	0
PILLAR	8	OK	0
FRONT WINDSHIELD	8	OK	0
SIDE VIEW MIRRORS	8	OK	0
LH FENDER	8	OK	0
LH FRONT DOOR	8	OK	0
LH REAR DOOR	8	OK	0
LH RUNNING BOARD	8	OK	0
LH QUARTER PANEL	8	OK	0
FUEL LID	8	OK	0
REAR WINDSHIELD	8	OK	0
REAR BUMPER	8	OK	0
TAIL LIGHT	8	OK	0
TRUNK LID/TAIL GATE	8	OK	0
LUGGAGE COMPARTMENT LIGHT	8	OK	0
RH QUARTER PANEL	7	OK	0
RH RUNNING BOARD	9	OK	0
RH REAR DOOR	8	OK	0

Ordered by: Shoab | Inspected date: 2018-10-05

Order Id: 26511

Overall Score



8/10



81,798



EXTERIOR (CONTINUED)





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	OK	0
RH FENDER	8	OK	0
BODY RUST	8	OK	0
ROOF (REGULAR)	8	COLOR FADED	0
PAINT CONDITION	7	PAINT FADED AND SCRATCHES	6000



IMAGES



DESCRIPTION

Some minor issues in door lock and paint faded. OK condition

Ordered by: Shoab | Inspected date: 2018-10-05

Order Id: 26511

Overall Score









8/10



81,798

IMAGES



Ordered by: Shoab | Inspected date: 2018-10-05

Order Id: 26511

Overall Score



8/10



81,798

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.