






Order ID : 30392

ECO INSPECTION CERTIFICATE

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.



Bajaj Platina 125CC, 2008

		VEHICL	E INFORM	TION		
AT A CON		MAKE	BAJAJ		LOCATION	GHAZIABAD
		MODEL	PLATINA		REGISTRATION NO.	XYZ
	The second	YEAR	2008		VIN/CHASIS NUMBER	XYZ
	1.	TRIM	125CC		KMS RUN	69441
		COLOR	RED		INSURANCE EXPIRY	2018-10-18
		FUEL TYPE	PETROL		ENGINE SOUND LINK	NIL
KEY OBSERVATIONS						
FLOOD DAMAGE	NO	A MAJOR AC	CIDENT(S)	NO	🚝 SERVICE LOGS AVAIL	ABLE NO
🌮 TYRE LIFE REMAINING (KM)	10,000		VAILABLE	NO	BANK HYPOTHECATIC	NO NO
🚔 DENT	NO	ansuranc 🙈	E COPY AVAILAE	BLENO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

39,380



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE









C

Order Id: 30392

Ordered by: Saquib | Inspected date: 2018-11-15

Overall Score

7/10



39,380

7/10

🍘 TYRE

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7		0
REAR TYRE CONDITION & AIR PRESSURE	7		0
WHEEL SPOKES FRONT	7		0
WHEEL SPOKES REAR	7		0
WHEEL RIM FRONT	7		0
WHEEL RIM REAR	7		0
WHEEL BEARINGS FRONT	7		0
WHEEL BEARINGS REAR	7		0
WHEEL SEALS FRONT	7		0
WHEEL SEALS REAR	7		0
BRAKE FUNCTION FRONT	7		0
BRAKE FUNCTION REAR	7		0
BRAKES CONDITION FRONT	7		0
BRAKES CONDITION REAR	7		0

E IMAGES









Order Id: 30392

Ordered by: Saquib | Inspected date: 2018-11-15

Overall Score

7/10



39,380

🕅 STAND

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7		0
CENTRE STAND RETENTION	7		0
SIDE STAND CONDITION	7		0
SIDE STAND RETENTION	7		0





		7/10		
INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)	
HANDLEBARS CONDITION	7		0	
LEVERS & PEDAL CONDITION	7		0	
PIVOTS	7		0	
CABLES CONDITION	7		0	
CABLES ROUTING	7		0	
HOSES CONDITION	7		0	
HOSES ROUTING	7		0	
THROTTLE OPERATION	7		0	





 \subset

Order Id: 30392

Ordered by: Saquib | Inspected date: 2018-11-15

Overall Score

7/10



39,380

🕞 IMAGES





🔊 OIL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7		0
LEVELS - GEAR OIL/SHAFT DRIVE	7		0
LEVELS - FUEL	7		0
LEAKS - ENGINE OIL	7		0
LEAKS - GEAR OIL	7		0
LEAKS - HYDRAULIC FLUID	7		0
LEAKS - COOLANT	7		0
LEAKS - FUEL	7		0









C

Order Id: 30392

Ordered by: Saquib | Inspected date: 2018-11-15

Overall Score

7/10



39,380

7/10

E LIGHT

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7		0
BATTERY VENT TUBE	7		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	7		0
TAILLAMP/BRAKELAMP OPERATION	7		0
TURN SIGNALS OPERATION FRONT LEFT	7		0
TURN SIGNALS OPERATION FRONT RIGHT	7		0
TURN SIGNALS OPERATION REAR LEFT	7		0
TURN SIGNALS OPERATION REAR RIGHT	7		0
SWITCHES OPERATION	7		0
MIRRORS CONDITION	7		0
MIRRORS AIM	7		0
LENSES & REFLECTORS CONDITION	7		0
WIRING CONDITION	7		0
	7		0







Order Id: 30392

Overall Score

Ordered by: Saquib | Inspected date: 2018-11-15

7/10



39,380

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	7		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	7		0
SUSPENSION FRONT FORKS RIGHT	7		0
SUSPENSION REAR SHOCKS LEFT	7		0
SUSPENSION REAR SHOCKS RIGHT	7		0
CHAIN/BELT TENSION	7		0
CHAIN/BELT LUBRICATION	7		0
CHAIN/BELT SPROCKETS	7		0
FASTENERS THREADED	7		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	7		0
TRANSMISSION	7		0
6			•

E IMAGES









Order ld: 30392





Vehicle OK





Ordered by: Saquib | Inspected date: 2018-11-15

Order Id: 30392

Overall Score

7/10



39,380

🕞 IMAGES































Order Id: 30392

Ordered b	by:	Saquib		Inspected	date:	2018-11-15
-----------	-----	--------	--	-----------	-------	------------

Overall Score

7/10



39,380

E DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

