


ECO INSPECTION CERTIFICATE

Premium

Order ID : 104766

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Delmon	Inspection Date : 2019-08-24	Location : ANDHERI	Inspected By  Verified Technician 77+ vehicle inspected 1+ years experience Abhishek TIWARI
------------------------	---------------------------------	-----------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

Renault Kwid RXL, 2017



VEHICLE INFORMATION

MAKE	RENAULT	ENGINE NUMBER	160489
MODEL	KWID	REGISTRATION NO.	MH02EP5681
MFG. DATE	06/2017	VIN/CHASSIS NUMBER	MEEBBA008H6507875
TRIM	RXL	ODOMETER READING	2132
COLOR	FIERY RED	INSURANCE EXPIRY	2019-9-3
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,70,993




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 6,000



Ordered by: Delmon | Inspected date: 2019-08-24

Order Id: 104766

Overall Score



7/10



2,70,993



INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD CONDITION	0
DOOR HINGES	8	GOOD CONDITION	0
CARPET & FLOOR MAT	8	GOOD CONDITION	0
SEAT & SEAT BELT	8	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD CONDITION	0
HORN	8	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	GOOD CONDITION	0
HANDBRAKE	8	GOOD CONDITION	0
PEDALS	8	GOOD CONDITION	0
CENTRAL LOCK	8	GOOD CONDITION	0
A/C VENTS & HEATER	8	GOOD CONDITION	0
CUP HOLDERS	8	GOOD CONDITION	0
ODOMETER	8	GOOD CONDITION	0
POWER WINDOWS (YES)	8	GOOD CONDITION	0
HAZARD LIGHT	8	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	0	NON-AVAILABLE/CRITICAL CONDITION	0
NAVIGATION (NO)	0		0



IMAGES



Ordered by: Delmon | Inspected date: 2019-08-24

Order Id: 104766

Overall Score **7/10**



2,70,993

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD CONDITION	0
BRAKE PERFORMANCE	8	GOOD CONDITION	0
CLUTCH PERFORMANCE	8	GOOD CONDITION	0
ENGINE NOISE	8	GOOD CONDITION	0
IGNITION SYSTEM	8	GOOD CONDITION	0
SUSPENSION PERFORMANCE	8	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	8	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	8	GOOD CONDITION	0
TRANSMISSION ENGAGE	8	GOOD CONDITION	0
REAR PARKING SENSORS (YES)	8	GOOD CONDITION	0
CRUISE CONTROL (NO)	0		0
REAR VIEW CAMERA (NO)	0		0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD CONDITION	0
SPARE TYRE (YES)	8	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	8	GOOD CONDITION	0





 IMAGES

 HOOD


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	NEUTRAL/AVERAGE CONDITION	0
RH APRON	6	NEUTRAL/AVERAGE CONDITION	0
RADIATOR	6	NEUTRAL/AVERAGE CONDITION	0
WIRING	6	NEUTRAL/AVERAGE CONDITION	0
BATTERY	6	NEUTRAL/AVERAGE CONDITION	0
BRAKE FLUID LEVEL	6	NEUTRAL/AVERAGE CONDITION	0
ENGINE OIL	6	NEUTRAL/AVERAGE CONDITION	0
COOLANT LEVEL	6	NEUTRAL/AVERAGE CONDITION	0
BRAKE & COOLANT HOSE PIPES	6	NEUTRAL/AVERAGE CONDITION	0
UNDERCARRIAGE	6	NEUTRAL/AVERAGE CONDITION	0
EXHAUST SYSTEM	6	NEUTRAL/AVERAGE CONDITION	0

 IMAGES



Ordered by: Delmon | Inspected date: 2019-08-24

Order Id: 104766

Overall Score  **7/10**



2,70,993

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	NEUTRAL/AVERAGE CONDITION	0
HEAD LIGHTS	8	GOOD CONDITION	0
GRILLE	8	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION	0
HOOD	8	GOOD CONDITION	0
PILLAR	8	GOOD CONDITION	0
FRONT WINDSHIELD	8	GOOD CONDITION	0
SIDE VIEW MIRRORS	6	NEUTRAL/AVERAGE CONDITION	0
LH FRONT DOOR	6	NEUTRAL/AVERAGE CONDITION	0
LH RUNNING BOARD	6	NEUTRAL/AVERAGE CONDITION	0
LH QUARTER PANEL	6	NEUTRAL/AVERAGE CONDITION	0
FUEL LID	6	NEUTRAL/AVERAGE CONDITION	0
REAR WINDSHIELD	6	NEUTRAL/AVERAGE CONDITION	0
REAR BUMPER	6	NEUTRAL/AVERAGE CONDITION	0
TAIL LIGHT	6	NEUTRAL/AVERAGE CONDITION	0
TRUNK LID/TAIL GATE	6	NEUTRAL/AVERAGE CONDITION	0
RH QUARTER PANEL	6	NEUTRAL/AVERAGE CONDITION	0
RH RUNNING BOARD	6	NEUTRAL/AVERAGE CONDITION	0
RH REAR DOOR	6	NEUTRAL/AVERAGE CONDITION	0

RH FRONT DOOR	6	NEUTRAL/AVERAGE CONDITION	0
BODY RUST	6	NEUTRAL/AVERAGE CONDITION	0
ROOF (REGULAR)	6	NEUTRAL/AVERAGE CONDITION	0
PAINT CONDITION	6	NEUTRAL/AVERAGE CONDITION	0
FRONT BUMPER	4	MINOR DAMAGE CONDITION	1500

Ordered by: Delmon | Inspected date: 2019-08-24

Order Id: 104766

Overall Score **7/10**



2,70,993

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FOG LAMPS	0	NON-AVAILABLE/CRITICAL CONDITION	0
LH FENDER	4	MINOR DAMAGE CONDITION	1500
LH REAR DOOR	4	MINOR DAMAGE CONDITION	1500
LUGGAGE COMPARTMENT LIGHT	0	NON-AVAILABLE/CRITICAL CONDITION	0
RH FENDER	4	MINOR DAMAGE CONDITION	1500

IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

car was good condition

Ordered by: Delmon | Inspected date: 2019-08-24

Order Id: 104766

Overall Score




7/10



2,70,993

🚗 IMAGES (61)





Ordered by: Delmon | Inspected date: 2019-08-24

Order Id: 104766

Overall Score



7/10



2,70,993

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.